






## 1. ACCESORIOS DE COBRE Y LATÓN, COBRE COMPRESIÓN



1.1 Accesorios de cobre JW. 100% de la gama certificada AENOR



ART. 5001 A

Curva 90° M-H



MEDIDA	CANTIDAD			€
	BOLSA	CAJA	UNIDAD	
10	25	1000	3,461	
12	25	600	1,188	
14	10	500	1,091	
15	25	450	0,941	
16	10	350	1,157	
18	25	250	1,466	
22	25	125	2,038	
28	10	70	5,642	
35	-	35	16,615	
42	-	20	24,942	
54	-	10	46,332	

ART. 5090

Codo 90° H-H



MEDIDA	CANTIDAD			€
	BOLSA	CAJA	UNIDAD	
10	10	1000	1,957	
12	10	500	0,683	
14	10	500	0,829	
15	25	500	0,685	
16	10	400	1,041	
18	25	350	1,006	
22	25	200	1,666	
28	10	90	2,766	
35	-	50	11,093	
42	-	30	18,191	
54	-	15	34,554	
64	-	-	83,906	
67	-	-	129,471	
76	-	-	170,167	
80	-	-	194,639	
108	-	-	400,519	

100% gama certificada

ART. 5002 A

Curva 90° H-H



MEDIDA	CANTIDAD			€
	BOLSA	CAJA	UNIDAD	
10	25	1000	1,514	
12	25	600	0,673	
14	10	500	1,118	
15	25	450	0,912	
16	10	350	1,075	
18	25	250	1,320	
22	25	125	2,048	
28	10	70	3,297	
35	-	35	9,105	
42	-	20	12,599	
54	-	10	35,554	
64	-	-	117,119	
67	-	-	146,946	
76	-	-	201,951	
80	-	-	261,381	

ART. 5092

Codo 90° M-H



MEDIDA	CANTIDAD			€
	BOLSA	CAJA	UNIDAD	
10	10	1000	3,089	
12	25	750	1,462	
14	10	500	0,958	
15	25	500	0,734	
16	10	400	1,157	
18	25	350	1,617	
22	25	200	2,498	
28	10	100	4,404	
35	-	50	17,463	
42	-	30	24,761	
54	-	15	48,073	
64	-	1	124,517	
67	-	1	161,597	

## ART. 5240

Manguito de reducción H-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	UNIDAD
12 x 10	25	1250	2,306
14 x 12	10	750	1,105
15 x 10	10	750	3,335
15 x 12	10	750	1,262
15 x 14	10	750	1,445
16 x 12	10	1250	1,382
16 x 14	10	600	1,105
16 x 15	10	600	2,229
18 x 12	25	600	3,042
18 x 14	10	600	1,823
18 x 15	25	600	1,055
18 x 16	10	500	1,886
22 x 12	10	400	6,684
22 x 14	10	350	2,781
22 x 15	25	350	2,894
22 x 16	10	350	2,976
22 x 18	25	350	1,970
28 x 12	10	200	10,928
28 x 15	10	200	6,390
28 x 18	10	200	6,228
28 x 22	10	180	3,089
35 x 18	-	125	18,891
35 x 22	-	125	12,372
35 x 28	-	125	15,201
42 x 28	-	75	21,787
42 x 35	-	60	17,047
54 x 42	-	35	32,646
64 x 54	-	-	49,652
67 x 54	-	-	76,022
76 x 54	-	-	81,436
76 x 64	-	-	79,969

## ART. 5243

Manguito de reducción M-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	UNIDAD
12 x 10	25	1250	1,936
14 x 12	10	1000	0,832
15 x 10	25	1000	2,131
15 x 12	25	1000	0,907
15 x 14	10	800	1,999
16 x 12	10	300	1,218
16 x 14	10	300	0,894
18 x 12	25	600	2,243
18 x 14	10	500	1,400
18 x 15	25	500	0,771
18 x 16	10	500	1,446
22 x 12	25	450	5,171
22 x 14	10	400	2,229
22 x 15	25	400	1,427
22 x 16	10	400	1,788
22 x 18	25	350	1,450
28 x 12	10	200	10,844
28 x 14	10	200	6,993
28 x 15	10	200	5,365
28 x 16	10	200	7,186
28 x 18	10	200	5,917
28 x 22	10	200	2,434
35 x 15	-	150	16,127
35 x 18	-	150	12,764
35 x 22	-	150	12,177
35 x 28	-	125	8,065
42 x 18	-	80	38,712
42 x 22	-	80	21,821
42 x 28	-	75	17,217
42 x 35	-	75	14,551
54 x 28	-	50	37,847
54 x 35	-	50	34,029
54 x 42	-	35	27,639
64 x 54	-	-	60,122
67 x 54	-	-	90,849
76 x 54	-	-	79,451
76 x 64	-	-	88,278
80 x 67	-	-	127,908

100% gama certificada

## ART. 5130

"T" H-H-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	UNIDAD
10	25	750	2,959
12	10	500	1,243
14	10	400	1,222
15	25	350	1,062
16	10	300	1,398
18	25	200	2,120
22	10	120	3,156
28	10	60	5,754
35	-	35	16,682
42	-	20	31,332
54	-	12	53,097
64	-	15	158,626
67	-	-	167,663
76	-	-	196,296
80	-	-	264,116
108	-	-	450,658

## ART. 5270

Manguito con tope H-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	UNIDAD
10	25	1250	0,505
12	10	750	0,421
14	10	750	0,461
15	25	750	0,383
16	10	600	0,536
18	25	500	0,598
22	25	300	0,964
28	10	150	1,748
35	-	90	4,341
42	-	60	8,292
54	-	30	14,032
64	-	-	40,661
67	-	-	48,415
76	-	-	54,088
80	-	-	71,701
108	-	-	136,840

## ART. 5130 R

"T" reducida  
H-H-H

AENOR

Producto  
Certificado100% gama  
certificada

MEDIDA	CANTIDAD		€
	BOLSA	CAJA	
12 x 10 x 10	25	600	8,178
12 x 14 x 12	10	300	3,301
12 x 15 x 12	25	400	6,453
14 x 12 x 12	10	400	2,499
14 x 12 x 14	10	400	1,738
14 x 14 x 12	10	300	2,180
14 x 18 x 14	10	300	4,017
14 x 22 x 14	10	300	7,787
15 x 12 x 12	25	450	4,830
15 x 12 x 15	25	400	2,375
15 x 15 x 12	25	350	6,144
15 x 18 x 15	10	250	5,952
15 x 22 x 15	25	175	12,633
16 x 12 x 12	25	750	3,695
16 x 12 x 14	10	350	2,830
16 x 12 x 16	10	300	2,585
16 x 14 x 12	25	350	4,226
16 x 14 x 14	10	350	2,585
16 x 14 x 16	10	300	1,982
16 x 16 x 14	25	700	2,732
16 x 22 x 16	25	300	8,241
18 x 12 x 12	25	300	11,151
18 x 12 x 15	25	250	9,984
18 x 12 x 16	25	600	6,228
18 x 12 x 18	25	300	4,161
18 x 14 x 14	10	250	4,924
18 x 14 x 18	10	250	2,553
18 x 15 x 12	25	250	12,339
18 x 15 x 15	25	225	2,894
18 x 15 x 18	25	250	1,757
18 x 16 x 16	25	225	5,235
18 x 16 x 18	25	250	4,830
18 x 18 x 12	25	200	13,462
18 x 18 x 14	25	250	5,035
18 x 18 x 15	25	200	3,526
18 x 22 x 18	25	150	8,160
18 x 28 x 18	10	80	24,564
22 x 12 x 12	10	200	13,275
22 x 12 x 22	10	170	8,895
22 x 14 x 14	10	180	8,827
22 x 14 x 22	10	170	4,455
22 x 15 x 15	10	170	5,235
22 x 15 x 18	10	170	5,791
22 x 15 x 22	10	160	2,482
22 x 16 x 16	10	150	7,982

MEDIDA	CANTIDAD		€
	BOLSA	CAJA	
22 x 16 x 22	10	160	4,681
22 x 18 x 15	10	150	11,510
22 x 18 x 18	10	120	6,192
22 x 18 x 22	10	140	3,806
22 x 22 x 12	10	130	14,925
22 x 22 x 15	10	120	7,937
22 x 22 x 16	10	120	8,811
22 x 22 x 18	10	120	9,398
22 x 28 x 22	10	80	15,967
28 x 12 x 28	10	100	18,435
28 x 15 x 15	10	100	20,420
28 x 15 x 22	10	100	15,827
28 x 15 x 28	10	100	5,803
28 x 16 x 28	10	100	12,859
28 x 18 x 15	10	70	21,946
28 x 18 x 18	10	70	22,341
28 x 18 x 22	10	80	14,713
28 x 18 x 28	10	80	10,210
28 x 22 x 15	10	70	23,411
28 x 22 x 18	10	70	21,150
28 x 22 x 22	10	70	11,999
28 x 22 x 28	10	70	6,472
28 x 28 x 15	10	70	23,266
28 x 28 x 18	10	60	20,110
28 x 28 x 22	10	60	15,851
28 x 35 x 28	-	50	30,548
35 x 15 x 35	-	60	27,935
35 x 18 x 35	-	60	28,876
35 x 22 x 22	-	50	41,440
35 x 22 x 28	-	50	25,817
35 x 22 x 35	-	50	18,616
35 x 28 x 22	-	35	38,838
35 x 28 x 28	-	35	26,498
35 x 28 x 35	-	35	26,566
35 x 35 x 22	-	35	47,389
35 x 35 x 28	-	35	44,790
42 x 22 x 42	-	30	41,050
42 x 28 x 42	-	30	45,311
42 x 35 x 35	-	25	72,736
42 x 35 x 42	-	25	56,155
42 x 42 x 28	-	20	76,801
54 x 22 x 54	-	20	89,954
54 x 28 x 54	-	20	97,708
54 x 35 x 54	-	15	97,836
54 x 42 x 54	-	12	98,601

## ART. 5040

Curva 45° M-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	
10	10	1000	4,537
12	25	1000	1,723
14	10	500	1,446
15	25	500	0,779
16	10	500	1,851
18	25	300	1,830
22	25	200	1,782
28	10	100	3,773
35	-	50	14,242
42	-	30	24,874
54	-	15	41,605
64	-	-	140,789
67	-	-	158,446
80	-	-	193,299

## ART. 5041

Curva 45° H-H



MEDIDA	CANTIDAD		€
	BOLSA	CAJA	
10	25	1000	4,032
12	25	750	2,505
14	10	500	1,201
15	25	500	0,841
16	10	500	1,333
18	25	300	1,797
22	25	200	2,062
28	10	100	3,694
35	-	50	12,926
42	-	30	22,762
54	-	15	41,605
64	-	20	143,294
67	-	-	146,927
76	-	-	171,516
80	-	-	193,784

ART. **5085**

Curva desviación  
H-H (puente)



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
12	10	200		9,105
14	10	140		9,217
15	10	130		4,432
16	10	100		10,292
18	10	80		11,956
22	5	60		16,015



ART. **5086**

Curva desviación  
M-H



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
12	10	250		8,160
14	10	160		8,388
15	10	180		4,051
16	10	100		9,430
18	10	130		9,934
22	5	70		13,885

ART. **5301**

Tapón hembra



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
10	25	2500		2,634
12	25	1500		2,131
14	25	1250		2,343
15	25	1250		1,122
16	25	1000		2,585
18	25	750		1,368
22	25	500		2,325
28	10	200		4,438
35	-	200		11,934
42	-	125		21,070
54	-	60		29,847

ART. **359 g Cu**

Racor Abocardado  
loco plano



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
15 x 1/2	25	700		1,495
15 x 3/4	25	500		2,516
18 x 1/2	25	500		1,820
18 x 3/4	25	400		2,326
22 x 1/2	25	400		4,057
22 x 3/4	25	300		2,528
22 x 1	10	250		4,079
28 x 3/4	25	250		5,382
28 x 1	10	150		4,607
28 x 1 1/4	10	100		7,404
35 x 1 1/4	10	100		8,955
42 x 1 1/2	10	60		11,629
54 x 2	5	40		23,202

ART. **359 g Cu**

Racor Abocardado  
normal



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
12 x 3/8	25	1000		1,618
12 x 1/2	25	800		1,483
14 x 3/8	25	700		1,708
14 x 1/2	25	700		1,595
15 x 3/8	25	1000		1,708
15 x 1/2	25	700		1,495
15 x 3/4	25	500		2,516
16 x 1/2	25	700		1,776
18 x 1/2	25	500		1,820
18 x 3/4	25	400		2,326
18 x 1	25	400		3,098
22 x 1/2	25	400		3,910
22 x 3/4	25	300		2,528
22 x 1	10	250		3,921
28 x 3/4	25	250		5,483
28 x 1	10	150		4,607
28 x 1 1/4	10	100		7,966
35 x 1 1/4	10	100		8,955
42 x 1 1/2	10	60		11,629
54 x 2	5	40		22,921
12 x 20/150	-	-		2,379
15 x 20/150	-	-		2,696

ART. **2 ag Cu**

Racor Curvo



CANTIDAD				€
MEDIDA	BOLSA	CAJA	UNIDAD	
12 x 3/8	25	700		2,484
12 x 1/2	25	500		2,573
14 x 1/2	25	500		2,404
15 x 1/2	25	500		2,382
15 x 3/4	25	300		3,865
16 x 1/2	25	500		2,516
18 x 1/2	25	400		2,731
18 x 3/4	25	250		3,865
18 x 1	25	250		3,397
22 x 3/4	25	200		3,967
22 x 1	10	150		6,214

## ART. 359 g Cu

Gas Racor Abocardado Precinto



CANTIDAD			€
MEDIDA	BOLSA	CAJA	UNIDAD
12 x 7/8	25	300	4,135
12 x 1/2	25	800	1,842
14 x 1/2	25	700	1,922
15 x 1/2	25	700	1,798
16 x 1/2	25	700	1,922
18 x 1/2	25	500	2,179
22 x 1/2	25	400	4,281
15 x 3/4	25	500	2,854
18 x 3/4	25	400	2,674
22 x 3/4	25	300	2,877
15 x 7/8	25	300	3,742
18 x 7/8	25	250	3,742
22 x 7/8	25	250	3,798
28 x 7/8	10	200	5,056
22 x 1	10	250	4,247
28 x 3/4	25	250	5,899
28 x 1	10	150	4,809
28 x 1 1/4	10	100	7,865
35 x 1 1/4	10	100	8,764
42 x 1 1/2	10	60	11,168
54 x 2	5	40	21,270

## ART. 359 g Cu

Racor Abocardado con toma de purgador



CANTIDAD			€
MEDIDA	BOLSA	CAJA	UNIDAD
15 x 1/2	25	400	11,618
15 x 3/4	25	250	11,618
15 x 7/8	25	150	11,618
18 x 3/4	25	200	11,618
18 x 7/8	25	150	11,618
22 x 7/8	25	150	11,618
22 x 3/4	25	200	11,618

## ART. 2 ag Cu

Gas Racor Curvo Precinto



CANTIDAD			€
MEDIDA	BOLSA	CAJA	UNIDAD
12 x 1/2	25	500	3,134
15 x 1/2	25	500	2,978
18 x 1/2	25	400	3,090
22 x 1/2	25	200	6,944
15 x 3/4	25	300	5,135
18 x 3/4	25	250	4,236
22 x 3/4	25	200	5,135
15 x 7/8	25	150	6,832
18 x 7/8	25	150	6,753
22 x 7/8	10	150	5,955
22 x 1	10	150	6,585
28 X 7/8	10	150	6,505

## ART. 420

Juntas de goma para art. 2 ag Cu y art. 359 g Cu



CANTIDAD			€
MEDIDA	BOLSA	CAJA	UNIDAD
3/8	100	-	0,08
1/2	100	-	0,13
3/4	100	-	0,15
1	100	-	0,23
1 1/4	50	-	0,32
1 1/2	50	-	0,38
2	50	-	0,46
7/8	100	-	0,18